



Service Data: Same as Model 150, TV page 2-1 through TV page 2-17

LINEARITY COIL  
Low Eye View

- ALL TUBES MUST BE REPLACED AT THE SAME TIME.
- ALL TUBES MUST BE REPLACED WITH THE SAME TYPE.
- ALL TUBES MUST BE REPLACED WITH THE SAME MANUFACTURER.
- SERVICE OF SETS AT CENTRAL SERVICE.

IF THE SET IS TO BE REPAIRED, AN APPROXIMATE TIME IS INDICATED.